

FLINT, BISHOP INT'L (FNT)

FREQ		
ATIS	133.15	
CLNC	121.75	
GND	121.9	
TWR/CTAF*	126.3	
GREAT LAKES		
APP/DEP (R)		
E/S	118.8	
W/N	128.55	
LANSING FSS		
RCO	122.3	
UNICOM	122.95	

LOCATION

12-19

782'

ELEV

09809.A
25-01

SKETCH

FNT

Taxiway
next pg

RWY LENGTH BEYOND DISPLACED THR

09/ — * 18/ 7648'

27/ — * 36/ —

COORDINATES

42° 57.93'N

083° 44.69'W

License
Air Carrier

FM CITY: 3.0 mi SW

LGT: ROTG BCN, HIRL, PAPI. Aft twr opn*
intsty pre-set. MALSRS rwy
09/27—STD PCL CTAF.

MGR: Antonino Sapone

PH: 810-235-6560

FBO: Avflight Flint 810-235-0681

ATND: 24 Hrs

NAV AIDS: IAP, 116.9 (FNT) at fld, NDB (FN)
269 KHz 097° 6.4 NM to fld, ILS.

FUEL: 100LL, JET A

RPR: Major A&P

WX: ASOS, DTN, ASOS 810-342-7804

SNW RMVL: Yes

TRNSP: Taxi, Rntl car (at arpt)

MEALS: At arpt

RON: Adj

- FAA Class "C" durg *twr hrs 0545-2330, otr times Class "E".
- Birds & deer on & invof arpt.
- Stanard TPA.
- LAHSO; ldg rwy 09 hold-short point 18/36 Measured distance 4100' GA only.
- LAHSO; ldg rwy 36 hold-short point 09/27 Measured distance 6300' GA only.

FLINT, BISHOP INT'L TAXIWAY


FREQ

ATIS	133.15
CLNC	121.75
GND	121.9
TWR/CTAF*	126.3
GREAT LAKES	
APP/DEP (R)	
E/S	118.8
W/N	128.55
LANSING FSS	
RCO	122.3
UNICOM	122.95

CAUTION: BE ALERT TO RUNWAY CROSSING CLEARANCES.
 READBACK OF ALL RUNWAY HOLDING INSTRUCTIONS IS REQUIRED.

782'

F



NOTE: Due to distance of tower from terminal ramp, ATIS unable to provide visual guidance or proportioning of aircraft. USE CAUTION.

* UNLIGHTED